

Fig. 1




Fig. 2




Fig. 3

This diagram shows an exploded perspective view of a mechanical assembly. At the top is a circular component 100 with a flange 20. Below it is a threaded component 30 with a central hole 16 and two side ports 32. A small circular component 40 is positioned above the threaded component. Below the threaded component is a base plate 10 with a central circular opening 12. The base plate has several raised features: 11, 13, 14, 15, and 17. A cylindrical component 22 is shown at the bottom, with a flange 23. A dashed line indicates the vertical alignment of the central hole 16 and the central opening 12.




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9

